## CSC Chronological Masterplan Update As Provided by Ken Brown on 2/6/18

## Mark,

2012

I've looked into my notes and done a little digging into some old photos etc., the following is the most complete schedule of projects that I was able to add to the archives.

These notes are for projects that I participated in. I know that the walkways indicated N4, S4 & N9 immediately preceded my stuff and I the work was overseen by Greta Mittman and some was performed by Anderson Jones. I believe it was 2004 & 2005.

Beginning 2006 we rebuilt N3, walkway associated with davits 1-16 & added associated Laser pad area BBL.(galvanized steel piles, primed framing, treated pine, Ipe' wood)

| 2007        | Rebuilt N7 walkway & butterfly storage pads. (Treated pine decking, Ipe') Also 2007 rebuilt N10 walkway and JO walkway & Opti storage area.                                                          |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 2008        | Rebuilt SFS south sail folding area, (please note that in this and the 2007 projects we reclaimed/ reused as many 3x3 square steel pilings as possible, primed steel framing, and composite decking) |
| 2008        | Rebuilt CB committee boat/ rescue boat davits @ tack room, galvanized pilings, and composite decking                                                                                                 |
| 2008 & 2009 | Rebuild S3 walkway @ davits 77-94. Galvanized pilings & framing, and composite decking.                                                                                                              |
| 2009        | Rebuilt N5 walkway and installed -added davits 201 & 202. Galvanized pilings & framing, and composite decking                                                                                        |
| 2009        | Took out existing wooden floating dock BBD and replace with existing floating dock.                                                                                                                  |
| 2010        | Rebuilt S6 walkway @ davits 153-162. Galvanized pilings & framing, composite decking                                                                                                                 |
| 2010        | Rebuilt N6 walkway @ davits 96-102 plus 163 & 164. Galvanized pilings and framing, and composite decking.                                                                                            |
| 2010        | Rebuilt S1 walkway & T pier associated with davits 57-75, galvanized pilings & framing, composite decking.                                                                                           |
| 2011        | Rebuilt VIP area, galvanized pilings & framing, composite decking.                                                                                                                                   |

Electrical replaced including conduit, wiring, breaker boxes, fixtures, etc.

| 2013        | Rebuilt area inside South Gate, tied in between gate and sailfold area galvanized pilings & framing, composite decking             |
|-------------|------------------------------------------------------------------------------------------------------------------------------------|
| 2013        | Overlay davits 25 & 26, N8 extend pad space for additional board boat (V15), Galvanized pilings & framing, composite decking.      |
| 2013        | Rebuilt GS South Gate roof package. Galvanized pilings & framing, cedar facade.                                                    |
| 2013        | Re-deck add ramp area adjacent to davit 28 galvanized pilings & framing, composite decking (unconfirmed dates)                     |
| 2014        | Rebuilt walkway North east pier at davit #1 and add Laser storage. Galvanized pilings, framing, composite decking & Abaco decking. |
| 2014 & 2015 | North east walkway & T Pier extending from Laser storage, galvanized pilings & framing, composite decking, added Keelboat davits.  |
| 2015        | Rebuilt transition area and common area @ davit 127, galvanized pilings & framing, composite decking.                              |
| 2016        | Rebuilt rescue boat davits 35, 36 & 37, galvanized pilings & framing, composite decking.                                           |
| 2016        | Take out floating dock & replace with fixed dock BB2, galvanized pilings & framing, composite decking.                             |
| 2016        | Rebuilt SFS2 south sail folding area associated with davits 168 & 169, galvanized pilings & framing, composite decking             |
| 2017        | Take out davits 18-21 and build 5 davits for snipe class sailboats                                                                 |
| 2017        | Rebuilt NW portion of SFN common area for juniors and board boats. Galvanized pilings & framing, composite decking.                |